

" Quality Alert "

ID #:

2017 QA-003

Part #:

CY Stems


Problem Description:

Under cut on CY stem can cause issues with tank filling

Containment Action:

Make sure stem end is flush with standard corner break

BAD



GOOD



Department Mgr: Ken McGuire

Quality Engineer: Matt King

Quality Director: Dave Besancenez

Team Fact. Signature:

Removal Date:

Distribution :

VERIFICATION OF TRAINING LOG

Topic: _____

Date: _____ Time: _____ Training Hours: _____

Facilitator's : _____

I certify that I have received, and understand the training topic listed above.

Attendees:

Employee's *Printed* Name

Employee's Signature

1 _____
2 _____
3 _____
4 _____
5 _____
6 _____
7 _____
8 _____
9 _____
10 _____
11 _____
12 _____
13 _____
14 _____
15 _____
16 _____
17 _____
18 _____
19 _____
20 _____
21 _____
22 _____

1 _____
2 _____
3 _____
4 _____
5 _____
6 _____
7 _____
8 _____
9 _____
10 _____
11 _____
12 _____
13 _____
14 _____
15 _____
16 _____
17 _____
18 _____
19 _____
20 _____
21 _____
22 _____