

Log ID:

3934011

☐ Obfuscate?

Contributor:

Jack Hill

☐ Crashed?

Incident Description:

An America Hexcopter took off in GUIDED mode (red) and was directed to fly to a waypoint immediately North West of its launch position. Instead, after an initial attempt to fly North, it headed South East. At that point, the RPIC issued a LAND command (green) followed by a HOVER command (purple) both of which were ignored. The RPIC then attempted to take manual control of the

▲

▼

sUAS Type

▼

Autopilot Type


▼

Ground Control Station

▼

Possible causes:

Unsure - but possibly a faulty magnometer. Also the area we were flying in has strong interference from local airport radar.



File upload:

Log file to upload

▼

Submit