



NO SUPPORT  
FLASHING UNDER  
DRIP FLASHING AS  
CALLED OUT IN  
DETAIL 01/A6.33

