



A photograph showing a blue metal corner joint. A red dashed box highlights a horizontal surface where there is a significant amount of excess paint, creating a thick, uneven layer. The background is a dark blue metal surface, and the foreground shows a light-colored horizontal metal beam and a wooden plank above a rocky ground.

CLEARLY NOT
ACCEPTABLE.
REMOVE EXCESS
PAINT.