



NO CHANGE IN
WALL AT JAMB.
FUR OUT WALL
TO BE FLUSH.