



ON TOP FLOOR,
BATTENS SHOULD
NOT BE BROOKEN
BY HORIZONTAL
JOINT. BATTEN
SHOLD EXTEND UP
TO PARAPET.

WORK WITH
DESIGN TEAM
AND QED TO FIX
OIL CANNING.

OIL CANNED SECTIONS DO NOT
MEET DESIGN INTENT AND ARE
NOT ACCEPTABLE AS INSTALLED.
LMC AND INSTALLER TO WORK
WITH THE DESIGN TEAM TO
CORRECT.
OPTION 1 - FACE PANEL TO BE
BACKED WITH RIGID INSULATION;
OPTION 2 - FACE PANEL
REINFORCED WITH HONEYCOMB
PANEL.