

METAL SHOULD BE  
CUT WITH STRAIGHT  
LINES. TYPICAL AT  
EVERY LOCATION.  
REMOVE AND  
REPLACE ALL NON  
CONFORMING  
FLASHING.

