



Category	Details
Project Name	x
Project ID	x
Project Location	x
Company Name	ICoM GmbH
Inspector Name	Max Mastermann
Date of Inspection	02/04/2025
Damage & Object Type(s)	JTape (Joint Tape), Weathering, Rust
Impact	The rust staining on the concrete surface and the joint tape (17) on the bridge structure.
Size	The rust staining appears to be relatively small, possibly in the range of 10-20 cm².
Direction	Horizontal (along the joint tape).
Possible Reasons	The rust staining could be attributed to environmental factors such as exposure to moisture and sunlight, which are common causes of rusting in concrete structures.