



Maybe unnecessary diodes

- TACO is chopped by PWM
- FAN_PWM should be held low while counting TACO
- Two rising edges per rotation

