





On the picture above we can see the platform split into two parts, one has its opacity a little lower to distinguish the difference.

At the end of the session, I started the impression of the part on the left, after coming back 30min it had failed and needed to be restarted.

Also during this session, I retrieved a new limit switch and welded wires to it and after some testing found out that one of the other switches had a bad weld and caused contact failures.