





76.0

These X mark the locations for the screw holes in the base (drill 13 holes). Do not pre-drill the holes for the guide bar machine screws.

59.0



35.0

35.0











