

This accident occurred while a pneumatic test was being carried out on a pipe that was connected to the tank. No blanking plate or figure eight was installed to isolate the tank from the circuit. Only the inlet valve to the tank was closed. The valve was leaking, causing the tank to become pressurized and fly off like a rocket. Note that the bottom of the tank was torn off the base.



