

Report of the mechanical evaluation of LT428

Finally, be informed you the mechanical evaluation report for the samples as follows.
Please advise how you can correct the problems.

1. A gap between front panel and upper cover

As shown on the attached photos, there is a gap between upper portion of the front panel and Upper cover of the case.

As it is the face of the LT428, do not you think it looks cheaper?




Photo 1: Front panel



Photo 2: Magnification of red square

2. Leader logo

The Leader logo on the front panel is not proper.

As shown on the attached photo, between L and E also E and R are touched. This should be separated and please see that our original logo is separated and the logo on an application SW from you is fine.



Photo 3: Leader logo

3. Projection of a screw

A screw that fastens a ground lead of AC inlet to the chassis is projected on the bottom of the chassis.

4. Need color samples

Please provide us color samples which you applied to the LT428 same manner as we sent you before.

We use them as our future references.

5. Strength of the screw M2.5

As the screws that fasten Side bracket or/and Blind plate for rack-mounting were changed from M3 to M2.5, we concern the strength. Please advise if the strength of M2.5 is enough to support the side bracket and the blind plate for rack-mounting and the reasons.