

# Mountinginstruction

## Important

Please be aware of following when soldering the Potmeters:

The potmeters are VERY heat sensitive.

When mounting, please keep the PCB in upright position. After mounting, please check PCB for possible short-circuit or bad soldering.

## ARBEJDSINSTRUKTION FOR GRUNDPRINT 4008 109 70830

POTMETER BOARD PM5664  
Print nr.

: 4008 109 70830  
: 4008 117 04643

1.0  
SAMLING

Printet monteres som model.

2.0  
MONTAGE

### OBS ! OBS !

Printet må ikke loddess i loddemaskinen, da potmetrene "vælder".  
Derfor skal hele printet håndloddess.

### MERE OBS ! VIGTIGT !

Potmetrene R-002, R-004, R-006

2515

2322 505 00107

Tåler ikke så meget varme, monter potmetrene til sidst,  
og stil printet på højkant når de loddess.

Efter lodning ses printet efter for kortslutninger og dårlige lodninger  
og nødvendige reparationer gennemføres.

3.0  
TOUCH-UP

Intet.

4.0  
EFTER-  
MONTAGE  
LODDESIDE

KUV/PCB-003: Montage af grundprint  
Komponentplaceringstegning  
Stykliste  
Model

5.0  
REFERENCER