



HOTLink II CYV15G0404DXB Video Evaluation Board Software Errata for Version 2.0b

The following are the known issues/errors with the Video Evaluation Board Software Version 2.0b. These issues and errors are only related to the software or FPGA code present in the board. None of these issues are related to the performance or functions of HOTLink II Device. These issues/errors will still allow the customer to evaluate the performance and features of the HOTLink II Device. These issues will be fixed in future releases of the GUI. For more information, please contact Cypress Technical Support at <http://www.cypress.com/support>

1. The color bar patterns generated by the FPGA will have RGB Gamut Errors. This will result in the presence of GAMUT errors in the output SDI stream when the data generated by the FPGA is selected as Color Bars.
2. The status button "Auto Rate Locked" is not supported when the secondary receivers of the channel are selected.