

Windshield Repair SA

901 SE Military Hwy #C051
San Antonio, TX 78214
windshieldrepairsa@gmail.com
2108900210

INVOICE

Invoice#: 0126 - 0123

Date: Jan 25, 2026

To:

Test Test
12345 Street
San Antonio, TX 78123
210-123-4567

Item	DESCRIPTION	QTY.	PRICE	TOTAL
1	2020 TOYOTA TUNDRA Windshield Replacement VIN 123456789ABCDEFGHJ	1	\$300.00	\$300.00

SUBTOTAL \$300.00

TOTAL \$300.00

PAID \$300.00

PAYMENT INFO

DUE DATE: Jan 25, 2026

CARD PAYMENT NOTICE: Card payments will appear on your bank statement as "Christian Trevino". Disputed charges that are confirmed as valid may be subject to a \$25 processing fee, in addition to the original service total.

**ADDITIONAL INFO**

Your purchase comes with 1 free rock chip repair, performed by Windshield Repair SA, if it should occur within the first year of your windshield replacement.

The chip must be the size of a quarter or smaller to qualify, and a mobile fee will apply if the service is performed outside of 1604. Not redeemable for cash value.

Thank you for your business!

WARRANTY REPLACEMENTS

Windshield Repair SA warrants that the installation or repair will be performed to the highest standards and will be free from defects in workmanship. All of our workmanship is guaranteed for the life of the vehicle, which includes wind noise and water leaks.

Exclusions include, but are not limited to:

- Damage resulting from auto collision, new rock chips or cracks
- Leaks caused by rust deterioration
- Aftermarket antennas or devices
- Damages caused by a dysfunctional door regulator
- Any issues arising from previous installations (or other work done to the vehicle) not performed by Windshield Repair SA.

Our liability under this warranty is limited to the repair or replacement of the auto glass. In the event of a water leak, it is the customer's responsibility to ensure the vehicle is kept away from rain & moisture. Windshield Repair SA is not liable for any incidental or consequential damages arising from the use or inability to use the auto glass.

This warranty is non-transferable and expires with the change of ownership of this vehicle.

If you experience any warranty issues, please contact us immediately at 210-890-0210 so we may evaluate the issue and take necessary action. These actions may include resealing, reinstalling, or repairing. Mobile fee may apply.

IMPORTANT - VEHICLES WITH LKAS & FORWARD COLLISION:

ADAS Driver Safety System Calibration

The customer acknowledges that certain windshields replaced by Windshield Repair SA may contain sensors for items such as lane departure mitigation, LKAS (lane keep assist), forward collision alert, or any other sensor which controls the vehicle's movement. Windshield Repair SA has provided notice that the vehicle manufacturer may require the windshield sensor to be recalibrated after the new windshield is installed. We always recommend recalibration be performed to ensure these critical sensors work effectively, for your safety. The customer acknowledges that if recalibration is NOT performed, these systems may malfunction at any time after installation, whether or not an indicator light or error code appears on the vehicle dashboard.

