

Windshield Repair SA

901 SE Military Hwy #C051
San Antonio, TX 78214
windshieldrepairsa@gmail.com
2108900210

INVOICE

Invoice#: 0126-0121

Date: Jan 22, 2026

To:

Connor Waldron
2842 Redsky Pass
SATX 78259
734-735-7705

Item	DESCRIPTION	QTY.	PRICE	TOTAL
1	ROCK CHIP REPAIR 2019 TOYOTA CAMRY VIN 4T1B11HK1KU237217	1	\$85.00	\$85.00
2	MOBILE FEE - Waived 1 time courtesy	1	\$0.00	\$0.00
3	3.5% transaction fee	1	\$2.98	\$2.98

SUBTOTAL \$87.98

DISCOUNT \$10.00

TOTAL \$77.98

PAID \$77.98

**PAYMENT INFO**

DUE DATE: Jan 22, 2026

CARD PAYMENT NOTICE: Card payments will appear on your bank statement as "Christian Trevino". Disputed charges that are confirmed as valid may be subject to a \$25 processing fee, in addition to the original service total.

ADDITIONAL INFO

Thank you for your business!

WARRANTY

Upon completion of the repair, we provide a lifetime warranty to ensure the chip or crack will not spread from its original repair location. In the event that the chip does spread, we will either:

- Perform a repair on the growth portion at no cost (IF the damage is deemed repairable by one of our technicians) a maximum of two times, OR
- Credit 40% of the amount paid for the original repair to be applied toward a full windshield replacement by our company (IF the damage is deemed NOT repairable by one of our technicians, including but not limited to: if it has grown more than 4 inches)

Please note that rock chip repair is primarily focused on restoring the structural integrity of the windshield, not for cosmetic improvement. You may still notice the chip or crack after the repair is completed - this is normal.

Due to the nature of the glass being pre-damaged, there is a possibility that the chip could spread during the repair process. This becomes even more likely with extreme weather (extreme heat and cold). If this is the case, we will not charge you for the attempted repair, however, we cannot guarantee the windshield against further damage.

If you experience any warranty issues, please contact us immediately at 210-890-0210 so we may evaluate the issue and take necessary action. These actions may include repairing spread or quoting for replacement if the spread is too large. Mobile fee may apply if a warranty appointment is scheduled but the chip or crack hasn't actually spread since the first repair.

