

# Tenda AC15(V15.03.05.19) has a Stack Buffer Overflow Vulnerability

---

## product

---

1. product information:
2. firmware download:

## Affected version

---

V15.03.05.19

## vulnerability

---

The stack overflow vulnerability is in /bin/httpd. The vulnerability occurs in the `formSetIpMacBind` function, which can be accessed through the URL `goform/SetIpMacBind`.