

main

...

CVE-vulns / tenda\_ac6 / setSchedWifi\_schedEndTime / setSchedWifi\_schedEndTime.md

Haizhen Qi(祁海珍) add

History

0 contributors

45 lines (30 sloc) | 3.31 KB

# Tenda AC6V1.0 V15.03.05.19 was discovered to contain a buffer overflow via the schedEndTime parameter in the setSchedWifi function.

## Description

Tenda Router AC6V1.0 V15.03.05.19 was discovered to contain a buffer overflow in the httpd module when handling /goform/openSchedWifi request.

## Firmware information

- Manufacturer's address: <https://www.tenda.com.cn/>
- Firmware download address : <https://www.tenda.com.cn/download/detail-2681.html>

## Affected version

AC6V1.0升级软件 **V15.03.05.19**

立即下载

关联产品: AC6v1.0 更新日期: 2017/5/27

- 1.此固件只适用于AC6V1.0的机器升级，不同型号不同硬件版本不能使用该软件，升级前请通过路由器底部贴纸确认产品型号和版本（如下图所示）；
- 2.修复部分bug;
- 3.增强设备安全;
- 4.升级方法：使用tendawifi.com登录到路由器管理界面，打开系统管理--软件升级--点击本地升级，浏览到下载解压后的“.bin”的文件，点击确定即可升级;
- 5.升级过程中切勿切断电源，否则会导致路由器损坏而无法使用！软件升级完成后需要将路由器恢复出厂设置并重新设置上网！



AC6V1.0:电源输入是12V-1A



AC6V2.0:电源输入是9V-1A

\* 如果链接错误或其他问题，请反馈到 [tenda@tenda.com.cn](mailto:tenda@tenda.com.cn)或联系在线客服，谢谢。

## Vulnerability details

This vulnerability lies in the /goform/openSchedWifi page, The details are shown below:

This POC can result in a Dos.

◀ ◻ ▶

```
Connect to server failed.  
Unsupported setsockopt level=1 optname=13  
Segmentation fault (core dumped)
```