

main ▾

...

vuln / TOTOLINK / A3700R / 9 / readme.md



Darry-lang1 Update readme.md

History

1 contributor



61 lines (40 sloc) | 2.6 KB

...

# TOTOLink A3700R V9.1.2u.6134\_B20201202 has a stack overflow vulnerability

## Overview

- Manufacturer's website information: <https://www.totolink.net/>
- Firmware download address : [http://www.totolink.cn/home/menu/detail.html?menu\\_listtpl=download&id=69&ids=36](http://www.totolink.cn/home/menu/detail.html?menu_listtpl=download&id=69&ids=36)

## Product Information

TOTOLink A3700R V9.1.2u.6134\_B20201202 router, the latest version of simulation overview:

编号	标题	版本	上传时间	下载
1	A3700R数据资料	Ver1.0	2021-08-10	
2	A3700R升级固件	V9.1.2u.6134_B20201202	2021-08-10	
3	A3700R说明书	Ver1.0	2022-03-10	

## Vulnerability details

```

nvram_set_int("rt_sta_auto", 0);
nvram_set_int("wl_mode_x", 0);
nvram_set_int("wl_sta_wisp", 0);
nvram_set_int("wl_sta_auto", 0);
nvram_set_int("crpc_enable", 0);
if ( strcmp(Var, "gw") )
{
    if ( !strcmp(Var, "br") )
    {
        nvram_set("wan_route_x", "IP_Bridged");
        nvram_set_int("sw_mode", 3);
        nvram_set_int("networkmap_fullscan", 0);
        nvram_set_int("dhcp_enable_x", 0);
        nvram_set("lan_proto_x", "1");
        nvram_set("rt_guest_lan_isolate", &word_43908C);
        nvram_set("wl_guest_lan_isolate", &word_43908C);
LABEL_19:
        sub_4253F4(a1);
        sub_426B50(a1);
        sub_426810(a1);
        goto LABEL_20;
    }
    if ( !strcmp(Var, "rpt") )

```

```

1 int __fastcall sub_4253F4(int a1)
2 {
3     int String; // $v0
4
5     String = cJSON_CreateString("1");
6     cJSON_AddItemToObject(a1, "switchOpMode", String);
7     sub_4241E0(a1);
8     return 1;
9 }

```

```

case 3:
strcpy(v61, "pppoe");
v11 = websGetVar(a1, "pppoeSpecType", (int)&word_43908C);
nvram_set("wan_pppoe_specType", v11);
v12 = websGetVar(a1, "pppoeUser", (int)&byte_43AFC8);
nvram_set("wan_pppoe_username", v12);
v13 = websGetVar(a1, "pppoePass", (int)&byte_43AFC8);
nvram_set("wan_pppoe_passwd", v13);
v14 = websGetVar(a1, "pppoeMtu", (int)"1492");
nvram_set("wan_pppoe_mtu", v14);
v15 = websGetVar(a1, "pppoeServiceName", (int)&byte_43AFC8);
nvram_set("wan_pppoe_service", v15);
v16 = websGetVar(a1, "pppoeAcName", (int)&byte_43AFC8);
nvram_set("wan_pppoe_ac", v16);
v17 = atoi(v11);
if ( v17 )
{
switch ( v17 )
{
case 1:
sprintf(v67, "\\n\\r%s", v12);
nvram_set("wan_pppoe_username_mm", v67);
break;

```

v12 is formatted into v67 through sprintf function, and v12 is the value of pppoeUser we enter. The size of the format string is not limited, resulting in stack overflow.

## Recurring vulnerabilities and POC

In order to reproduce the vulnerability, the following steps can be followed:

1. Boot the firmware by qemu-system or other ways (real machine)
2. Attack with the following POC attacks

[illegible]



```
BusyBox v1.24.2 (2020-12-02 18:57:43 CST) built-in shell (ash)
Enter 'help' for a list of built-in commands.
```

```
/ # ls -l
drwxrwxr-x  2 1000      1000      4096 Jul 19 22:40 bin
drwxrwxr-x  3 1000      1000      4096 Dec  2  2020 dev
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 etc
drwxrwxr-x  4 1000      1000      4096 Dec  2  2020 etc_ro
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 home
lrwxrwxrwx  1 1000      1000           7 Dec  2  2020 init -> sbin/rc
drwxrwxr-x  3 1000      1000      4096 Dec  2  2020 lib
drwxrwxr-x  3 1000      1000      4096 Dec  2  2020 lighttp
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 media
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 mnt
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 opt
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 proc
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 sbin
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 sys
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 tmp
drwxrwxr-x  9 1000      1000      4096 Dec  2  2020 usr
drwxrwxr-x  2 1000      1000      4096 Dec  2  2020 var
drwxrwxr-x  9 1000      1000      4096 Dec  2  2020 www
/ #
```

Finally, you can write exp to get a stable root shell without authorization.