

main

...

CVE-vulns / tenda_i22 / formWifiMacFilterSet / formWifiMacFilterSet.md

Haizhen Qi(祁海珍) add i22

History

0 contributors

46 lines (31 sloc) | 3.44 KB

...

Tenda i22 V1.0.0.3(4687) was discovered to contain a buffer overflow via the index parameter in the formWifiMacFilterSet function.

Description

Tenda Router i22 V1.0.0.3(4687) was discovered to contain a buffer overflow in the httpd module when handling /goform/WifiMacFilterSet request.

Firmware information

- Manufacturer's address: <https://www.tenda.com.cn/>
- Firmware download address : <https://www.tenda.com.cn/download/detail-2747.html>

Affected version

i22

i22 1200M 高密度带机100人吸顶AP [资料下载](#)
首页 / i22 / 资料下载

i22升级软件 V1.0.0.3(4687)

立即下载

关联产品: i22 更新日期: 2017/11/3

- 此固件只适用于i22目前软件版本为V1.0.0.X的机器升级, 不同型号机器不能使用该软件, 升级前请确认版本;
- 下载解压后, 请使用有线连接机器升级, 升级过程中切勿切断电源, 否则会导致机器损坏无法使用!

* 如果链接错误或其他问题, 请反馈到 tenda@tenda.com.cn或联系在线客服, 谢谢。

Vulnerability details

This vulnerability lies in the /goform/WifiMacFilterSet page, The details are shown below:

[illegible][illegible]