

<b>GILES CHEMICAL CORPORATION</b>			
<b>COMPANY PROCEDURE</b>			
<b>Standard Operating Conditions</b>		Page : 1 of 1	Revision : Date : 7/18/2006
Author: Patrick Owen	Title: (00) Process Temperatures		

**Personnel responsible:**

1. Lead Operator, Material Handler, Assistant Operator

**Safety equipment:**

Safety glasses and safety shoes.

**Procedure:**

1. The Dryer Salt Temperature needs to stay within 34-37 degrees C. If at all possible, the salt should not exceed 38 C. If you are running Cumberland or Arch and the temperature goes outside of this range, you need to pull off and go to another product.
2. If the Crystallizer Temperature goes above 34 C, the Crystallizer needs to be shut down until it cools off to below 34 C.

## TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

GILES CHEMICAL CORPORATION			
COMPANY PROCEDURE			
Standard Operating Conditions		Page : 2 of 1	Revision : Date : 7/18/2006
Author:	Patrick Owen Title: (00) Process Temperatures		

15				
16				
17				
18				
19				
20				