



H.E. Woolley

Fire Protection & Security



1a Startforth Road, Riverside Park, Middlesbrough TS2 1PT.

Tel: 01642 247337 Email: info@he-woolley.co.uk

www.fireriskassessment.com

Certificate of Inspection of Fire Alarm

We being the competent persons responsible for the servicing of the fire alarm system, particulars set out below certify that the said work for which we have been responsible complies to the best of our knowledge and belief with the recommendations of Clause 45 of BS 5839-1:2017 periodic service except for the variations stated in this certificate.

Customer	AVL + Intratec - Units 8, 9 + 10	Date	9/10/23
Address	Easter Park, Riverside Ind Est., Middlesbrough	Order No.	
Invoice Address if different from above		Account Ref.	
		Invoice No.	

CALL OUT	<input type="checkbox"/>	FIRE ALARM			LAST SERVICE DATE		
OUT OF HOURS CALL OUT	<input type="checkbox"/>	SERVICED	25% <input type="checkbox"/>	50% <input type="checkbox"/>	100% <input checked="" type="checkbox"/>	NEXT SERVICE DATE	APR 24
ADDITIONAL HOURS	+5 <input checked="" type="checkbox"/>	WHOLE SYSTEM	<input checked="" type="checkbox"/>	SUB SYSTEM	<input type="checkbox"/>	CURRENT BAFE CERTIFICATE OF COMPLIANCE	YES <input type="checkbox"/> NO <input type="checkbox"/>

VARIATIONS FROM THE RECOMMENDATIONS OF CLAUSE 45:

- ☐ 12 MONTHLY SERVICE INTERVALS
☐ MISSING DEVICES
☐ BELLS NOT TESTED

Relevant details of the work carried out and the faults identified have been entered in the system log book ☒

During the past 12 months 0 false alarms have occurred

The above number of false alarms equates to 0 per 100 automatic fire detections per annum.

For type M systems, enter N/A.

SPARES	CONV.	ADDR.	NOTES
Panel			
Detector - smoke			
Detector - heat			
Detector - base			
Sounder			
Call Point			
Call Point IP67			
Battery 1amp-3amp			
Battery 3amp-7amp	2		12v 7.0ah
Battery 12amp-24amp			
Spare Glass			
Aspirator Filter			
Door Magnet			

NOTES:

Replaced batteries in Fire Panel.

Units 10 all functioning correctly - rec 1x SID be resided GLF near as to close to wall.

Unit 9 offices all ok, 1x SID needs refilling to GLF training room

" 9 Warehouse - 3x SID require re-wiring to fire system

Unit 8 - Densets in offices need re-wiring to the fire system along with 4x Roof Detectors. 2x new SIDs in stores, entrance & 1st office

Unit 8 & 9 currently has the centre Detectors in Warehouse functioning correctly

- HE Woolley Ltd is not responsible for any installation or alteration made by others at any time to any equipment included in this certificate. The certificate is subject to our conditions of sale, copies of which are available upon request.
- It is the client's responsibility to ensure that a weekly test of the alarm system and a monthly check of the emergency lights are performed by the nominated fire/safety officer in order to ensure correct operation. The system log book should be completed accordingly.

Engineer's Signature		Print	P. Hutchinson	Total	
Customer's Signature				VAT	
Print Name	M. Alex			Total	
Position	ENGINEER	Date	9/10/23		