

STORAGE EQUIPMENT SAFETY SERVICE
THE NATIONAL WAREHOUSE SAFETY CENTRE
UNIT 8, TRAFALGAR COURT
SOUTH NELSON ROAD
SOUTH NELSON IND. EST.
CRAMLINGTON, NORTHUMBERLAND, NE23 1EG
TEL: 01670 736444 - FAX: 01670 739903

CLIENT: Infratec UK Ltd
DEPOT: Infratec UK Ltd
Unit 8 & 9 Easter Park
Middlesbrough, TS2 1RY
SITE: Middlesbrough

DATE OF INSPECTION: 29/04/2025 11:30
JOB REFERENCE: 246393
ORDER NO:
INSPECTOR: Roxanne Reid

1

DAMAGE REPORT/COMPLETION CERTIFICATE

TO IGNORE THIS REPORT COULD RESULT IN A COLLAPSE OF THE STORAGE EQUIPMENT

Damaged components should be treated as per the risk category designated on the inspection sheets

Components in risk categories Red/Amber have damage which is in excess of that permitted in SEMA/FEM Guidelines for the Safe Use of Static Steel Racking and Shelving User's Code

To make the structure safe and to ensure the safety of your employees the following action should be implemented:

- R RED - [UNSAFE CONDITION ACTION REQUIRED, OFF-LOAD/MAKE SAFE].**
- A AMBER - [UNSAFE CONDITION ACTION REQUIRED WITHIN TIME INDICATED ON THE FOLLOWING INSPECTION SHEETS].**
- G GREEN - [SAFE CONDITION PERIODIC MONITORING REQUIRED].**

Signed for SESS:




Name: Roxanne Reid

Date: 29/04/2025 12:25

Client Acceptance

I confirm that the SAFETY INSPECTION has been completed in full. I also confirm that I have received a copy of the report and have been briefed on the findings.

Signed By:



Name: Lee Bullock

Position:

Date: 29/04/2025 12:25

PLEASE NOTE: THIS REPORT SHOULD ALWAYS BE VIEWED OR PHOTOCOPIED IN COLOUR

A

Amber - [Off-Load as indicated]

AMBER-RISK [OFF-LOAD/REPAIR WITHIN 4 WEEKS - DO NOT RELOAD UNTIL RECOMMENDED REPAIRS ARE COMPLETED]

Manufacturer: None

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-SITE	(ALL/	N/A	Clipped	Observations	Front	-	-	1	-

Many deck support bars are missing or loose in the Storalex shelving in runs 05, 06, 07, 08 and 11. Replace missing support bars or re-fix loose ones.

Manufacturer: Storalex

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Mezzanine-07	(ALL/	N/A	Clipped	Complete Rack	N/A	Incorrectly Installed	Re-install	1	-

Beams missing or detached which limits stability.

G

Green - [Periodic monitoring required]

Manufacturer: AR Sistemas L/S

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-02	(ALL/	All	Bolted	Safety Lock	Both	Missing	Monitor	33	-
Handloaded, no MHE.									
.-Main-02	(ALL/	N/A	Bolted	Floor Fixing	Both	Missing	Monitor	22	-
Handloaded. No MHE.									
.-Main-02	(Beg/C	N/A	Bolted	Upright Post	Front	Damaged	Monitor	1	-
.-Main-02	A-	3	Bolted	Beam	Front	Damaged	Monitor	1	-
Drill holes in beam.									
.-Main-02	C-	All	Bolted	Beam	Both	Damaged	Monitor	4	-
Drill holes in beams.									
.-Main-02	D-	All	Bolted	Beam	Front	Damaged	Monitor	3	-
Drill holes in beams.									
.-Main-02	E-	1-3	Bolted	Beam	Front	Damaged	Monitor	2	-
Drill holes in beam.									
.-Main-02	F-	All	Bolted	Beam	Both	Damaged	Monitor	6	-
Drill holes in beams.									

G

Green - [Periodic monitoring required]

Manufacturer: AR Sistemas L/S

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-02	H/End)	1	Bolted	Bracing Horizontal	N/A	Damaged	Monitor	1	-
.-Main-08	(ALL/	All	Bolted	Safety Lock	Both	Missing	Monitor	20	-

Handloaded. No MHE.

.-Main-08	(ALL/	N/A	Bolted	Frame	N/A	Incorrect Orientation	Monitor	1	-
.-Main-10	(ALL/	All	Bolted	Safety Lock	Both	Missing	Monitor	26	-
.-Main-10	A/B	1	Bolted	Bracing Diagonal	N/A	Damaged	Monitor	1	-
.-Main-10	B/C	N/A	Bolted	Upright Post	Front	Damaged	Monitor	1	-
.-Main-10	C-	All	Bolted	Beam	Front	Damaged	Monitor	3	-

Drill holes in beams.


Manufacturer: Hi-Lo

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-03	(ALL/	N/A	Bolted	Frame	N/A	Incorrect Orientation	Monitor	2	-
.-Main-03	(ALL/	All	Bolted	Safety Lock	Both	Missing	Monitor	24	-

Handloaded. No MHE.

.-Main-03	(ALL/	N/A	Bolted	Floor Fixing	Both	Missing	Monitor	10	-
-----------	-------	-----	--------	--------------	------	---------	---------	----	---

Handloaded. No MHE.



Manufacturer: *Link 51 Boltless XL*

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-01	D-	3	Bolted	Beam	Front	Damaged	Monitor	1	-
.-Main-01	E/End)	N/A	Bolted	Upright Post	Front	Damaged	Monitor	1	-
.-Main-09	(ALL/	N/A	Bolted	Observations	Front	-	-	1	-

Limited access to inspect

.-Main-09	(ALL/	N/A	Bolted	Frame	N/A	Incorrect Orientation	Monitor	2	-
-----------	-------	-----	--------	-------	-----	-----------------------	---------	---	---

Manufacturer: *Mezzanine Floor*

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Mezzanine-MEZZ	(ALL/	N/A	Bolted	Observations	Front	-	-	1	-

Minor damage to plate protecting decking at pallet gate.

.-Mezzanine-MEZZ	(ALL/	N/A	Bolted	Joist	N/A	Damaged	Monitor	1	-
------------------	-------	-----	--------	-------	-----	---------	---------	---	---

Underneath pallet gate at the edge of the floor.

Manufacturer: *Storalex*

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-08	A-	1	Clipped	Beam	Front	Damaged	Monitor	1	-

Floor level.



Manufacturer: *Unknown L/Span*

WH-AREA-RACK	LOCATION	LEVEL	FRAME TYPE	COMPONENT	POSITION	DEFECT	ACTION	QTY	REPAIR
.-Main-04	(ALL/	All	Welded	Safety Lock	Both	Missing	Monitor	32	-

Handloaded. No MHE.

.-Main-04	(ALL/	N/A	Welded	Floor Fixing	Both	Missing	Monitor	8	-
-----------	-------	-----	--------	--------------	------	---------	---------	---	---

Handloaded. No MHE.