

(Section A) - NATURE OF NCR:

NCR #: 009/22


Actual Non-Conformity
Potential Non-Conformity
☐ SUPPLIER DEFAULT ☐ INTERNAL DEFICIENCY ☐ CUSTOMER COMPLAINT ☐ OTHER ☐ PREVENTIVE ACTION

SYSTEM AFFECTED:
☐ ROAD TRAFFIC SAFETY

☐ ENVIRONMENTAL

(Section B) - DESCRIPTION OF PROBLEM/ EFFECT:

Increase oil bund storage size.

(Section C) - ROOT CAUSE ANALYSIS:
(Mark appropriate cause)

Details of Root Cause: The volume of oil stored in the oil bund exceeded the bund capacity

INITIATOR: R Singh

DEPT: Management

DATE: 12/01/2022

(Section D) - CONTAINMENT ACTION (IMMEDIATE):
RESP
TARGET DATE
STATUS

1. Remove oil drums and ensure that oil stored in the bund does not exceed the maximum bund capacity

Leroy

14/01/2022

Done

2.

(Section E) - CORRECTIVE ACTION (SHORT TERM):
RESP
TARGET DATE
STATUS

1 Ensure there is enough space to store oil in the bund before placing an order for more oil

Leroy

Ongoing

Done

2.

(Section F) - PREVENTIVE ACTION (LONG TERM):
RESP
TARGET DATE
STATUS

1. Increase bund capacity

Leroy

01/03/2022

Open

2.

(Section F) - VERIFY EFFECTIVENESS OF ACTIONS TAKEN:
☐ Problem still occurring. No noticeable differences since actions implemented

☐ Problem still occurring, however less frequently

☐ Problem still occurring very rarely

☒ Problem effectively rectified. No further occurrences since actions taken

☐ (Other)

VERIFIED BY:

DATE: