



A diagram of a rectangular plate with rounded corners. Inside the plate, seven 'x' marks indicate the locations of drill holes. The holes are arranged in three rows: the top row has two holes on the left and one on the right; the middle row has one hole centered; the bottom row has two holes on the left and one on the right. The horizontal spacing between the left and right holes in each row is wider than the vertical spacing between the rows.

x x x
 x
x x x

Drill Map:
x 1.200mm / 0.0472" (7 holes) (not plated)