



R19 is a zero ohm resistor that should be installed in lieu of the 2-pin jumper for production units only, following the final programming of U1.

Layout J11 and J10.1 in
a 0.100" spacing
configuration.

