

AttenuatorX - Bug # 119: No strain relief was provided for the battery connection.

Status:	New	Priority:	High
Author:	Jack Linke	Category:	
Created:	02/11/2013	Assignee:	
Updated:	02/11/2013	Due date:	
Subject:	No strain relief was provided for the battery connection.		
Description			
Identify and implement a good way of providing relief.			

History