

AttenuatorX - Bug # 115: The header should be SMT (as I already determined in the BOM), not through-hole (as I designed the board), and it should be on the bottom of the board.

Status:	New	Priority:	Normal
Author:	Jack Linke	Category:	
Created:	02/11/2013	Assignee:	
Updated:	02/11/2013	Due date:	
Subject:	The header should be SMT (as I already determined in the BOM), not through-hole (as I designed the board), and it should be on the bottom of the board.		
Description			
For now I'm just making do with through-hole headers.			

History
