



Photo 1



Photo 2





Photo 3



**broken concrete, exposed  
rusting rebar, and wooden  
shim under east span**

Photo 4



Photo 5





**significant cracks in  
concrete pier**

Photo 6

close up of significant  
cracks in center bridge  
pier




Photo 7





Photo 8





**bridge steel of varying  
ages and condition**

Photo 9