







When routing the PCB it was found to be more expedient to change the way the sensors were connected to the multiplexer ICs, resulting in a slight problem for a programmer using this board. Please be careful when assigning variables to pins.

Rev: 1
Id: 3/3