




Pin 2 on FRM is used for an open collector to ground for frame advance
 LS is for an LDR to control the display LCD brightness.
 The battery sensor is to detect the battery voltage. It does not power the device.



LED Ports 3 and 4.
 Can't use if peripheral port is used.

Some PCB versions have separate pins for the LED data while others have 3 pins for each LED. The GND and +5 are not needed on those.



TITLE: External Wiring		REV: 1.1
	Company: Nohr Photo	Sheet: 1/1
	Date: 2020-09-08	Drawn By: MartinNohr