

Venue	LUM Fukuoka		Lot No.	9039	Score	4	Start price	¥0
Year	R1	Car Name	Corolla Axio		Grade			
Model	DAA-NKE165	Chassis number	NKE165-7226311		Color	Other	Gear	AT
Engine	1500cc	Mileage	85K km		Fuel		Car history	
Equipment	PS Record List Guarantee AC				Inspection	/00	Air conditioner	
Special note	Control number: 3241203-09039 5-seater First year: November 2019 Recycled: 9,470 yen Drive: 2WD Model designation: 17572 Classification: 0011 Deleted Mileage: 84,358 km Size: Compact							

開催 No.	出品 No.	会場名	評価点	内装評価点	修復歴
3241203	09039	LUM福岡	4	C	
引取先	福岡県北九州市門司区新門司北2-7-1				

AC
PS
保証書
記録簿
検付自賠責

31 フォグ
32 ヘッドライト
33 ウィンカー
34 アウターミラー
35 サイドウィンドウワiper
36 フロント
37 リア 荷室
38 テールランプ
39 バンパーランプ

1 フォグ
2 ヘッドライト
3 ウィンカー
4 アウターミラー
5 サイドウィンドウワiper
6 フロント
7 リア
8 荷室
9 テールランプ
10 バンパーランプ
11 バンパー
12 クロスメンバー
13 サイドメンバー
14 インサート
15 フロア
16 セットバック (キャブ背)
17 セットバック (キャブ背)
18 セットバック (キャブ背)
19 セットバック (キャブ背)
20 セットバック (キャブ背)
21 セットバック (キャブ背)
22 セットバック (キャブ背)
23 セットバック (キャブ背)
24 セットバック (キャブ背)
25 セットバック (キャブ背)
26 セットバック (キャブ背)
27 セットバック (キャブ背)
28 セットバック (キャブ背)
29 セットバック (キャブ背)
30 セットバック (キャブ背)

※下記表の瑕疵の部位については画像を確認して下さい

[illegible]

特記事項

ガラスヒビ シートスレ ハンドルスレ トリムキズ

■グループBのA1／U1／C1は、クレーム対象外です。

グループ区分	押曲率	交換歴	交換D	修復歴	修理D	線キズ	凹み	腐食	凹&傷	看板跡	ヒビ/割	交換跡	修理跡	塗装跡	指定塗
B	D/U	X	DX/XD	W	DW/WD	A1-4	U1-4	C1-4	B1-4	P1-4	G/Z	XX	W1-3	P	指

