

Venue	LUM Fukuoka		Lot No.	3564	Score	4	Start price	¥0
Year	R1	Car Name	Corolla Axio		Grade			
Model	DAA-NKE165	Chassis number	NKE165-7226909		Color	Other	Gear	AT
Engine	1500cc	Mileage	29K km		Fuel		Car history	
Equipment	PS Guarantee AC				Inspection	/00	Air conditioner	
Special note	Control number: 3241203-03564 5-seater First year: November 2019 Recycled: 9,470 yen Drive: 2WD Model designation: 17572 Classification: 0011 Deleted Mileage: 28,349 km Size: Compact							

開催 No.	出品 No.	会場名	評価点	内装評価点	修復歴
3241203	03564	LUM福岡	4	B	
引取先	福岡県福岡市東区蒲田4-368				

コアサポート

ロアサポート

パンパーホースメント

サイドメンバー突起部

クロスメンバー

サイドメンバー

インサイドパネル

フロア（キャブ床）

ビラーインナー

A B

ダッシュパネル

センターフロア

ルーフパネル

サイドシルインナー

フロアサイドメンバー

セットバック（キャブ側）

ビラーインナー

C D

トランクフロア

インサイドパネル

サイドメンバー

クロスメンバー

バックパネル

バンパーフォースメント

下回り

フグ 21

ヘッドライト 22

ウィンカー 23

アクターミラー 24

サイドウィンドウー

フロント 25

リア 26

荷室 27

テールランプ 28

バンパーランプ 29

AC PS 保証書 記録簿 検付自賠責

31 フグ

32 ヘッドライト

33 ウィンカー

34 アクターミラー

サイドウィンドウー

35 フロント

36 リア

37 荷室

38 テールランプ

39 バンパーランプ

*下記表の瑕疵の部位については画像を確認して下さい

部位名称	部位番号	瑕疵記号	部位名称	部位番号	瑕疵記号
Fバンパー	6	A1			
ボンネット	8	A1			
右Fドア	15	A1			
右Rフェンダー	17	A1			
部位なし	-	内外			
左Rドア	4	A1			

特記事項														
<input type="checkbox"/> ガラスヒビ シートスレ														

■グループBのA 1／U 1／C 1は、クレーム対象外です。

グループ区分	押曲歪	交換歴	交換D	修復歴	修理D	線寸ズ	凹み	腐食	凹 & 傷	看板跡	ヒビ割れ	交換跡	修理跡	塗装跡	指定塗
B	D/U	X	DX/XD	W	DW/WD	A1-4	U1-4	C1-4	B1-4	P1-4	G/Z	XX	W1-3	P	指

