



Indian Institute of Technology Bhubaneswar
School of Infrastructure

Subject Name : Solid Mechanics

Subject Code: CE2L001

Tutorial No. 6

1. A 45-degree strain rosette is used to measure strains on a steel surface. The readings are $\epsilon_a = 100 \mu\text{m/m}$, $\epsilon_b = 400 \mu\text{m/m}$, and $\epsilon_c = 900 \mu\text{m/m}$. Determine the principal strains and stresses.

Solution: Calculate strain components ϵ_{11} , ϵ_{22} , and γ_{12} :

$$\epsilon_{11} = \epsilon_a = 100 \mu\text{m/m}$$

$$\epsilon_{22} = \epsilon_c = 900 \mu\text{m/m}$$

$$\gamma_{12} = 2\epsilon_b - (\epsilon_a + \epsilon_c) = 2 \times 400 - (100 + 900) = -200 \mu\text{m/m}$$

Calculate principal strains:

$$\begin{aligned}\epsilon_{I,II} &= \frac{\epsilon_{11} + \epsilon_{22}}{2} \pm \sqrt{\left(\frac{\epsilon_{11} - \epsilon_{22}}{2}\right)^2 + \left(\frac{\gamma_{12}}{2}\right)^2} \\ \epsilon_{I,II} &= \frac{100 + 900}{2} \pm \sqrt{\left(\frac{100 - 900}{2}\right)^2 + \left(\frac{-200}{2}\right)^2} \\ \epsilon_I &= 912.31 \mu\text{m/m}, \quad \epsilon_{II} = 87.69 \mu\text{m/m}\end{aligned}$$

Calculate principal stresses:

$$\begin{aligned}\sigma_I &= \frac{E}{1 - \nu^2}(\epsilon_I + \nu\epsilon_{II}) \\ \sigma_{II} &= \frac{E}{1 - \nu^2}(\epsilon_{II} + \nu\epsilon_I)\end{aligned}$$

For a given steel with $E = 205 \text{ GPa}$ and $\nu = 0.29$, we can calculate the principal stresses as $\sigma_I = 209.85 \text{ MPa}$ and $\sigma_{II} = 78.83 \text{ MPa}$.

2. Consider a 60° strain gauge rosette to be mounted on the surface of a specimen as shown in Fig. 1.




Figure 1: Schematic representation of a 60° strain-gauge rosette.

- (a) Let $\{\mathbf{e}_a, \mathbf{e}_b, \mathbf{e}_c\}$ denote three non-collinear unit vectors which represent the directions in which the three strain gauges in a rosette are arranged, and let

$$E_{aa} = \mathbf{e}_a \cdot \mathbf{E} \mathbf{e}_a, \quad E_{bb} = \mathbf{e}_b \cdot \mathbf{E} \mathbf{e}_b, \quad E_{cc} = \mathbf{e}_c \cdot \mathbf{E} \mathbf{e}_c,$$

denote the components of the strain measured in the directions $\{\mathbf{e}_a, \mathbf{e}_b, \mathbf{e}_c\}$. Determine a general expression for the components of strain, \mathbf{E} , (i.e $E_{11}, E_{22}, E_{12} = E_{21}$) with respect to the basis $\{\mathbf{e}_1, \mathbf{e}_2\}$, as functions of (E_{aa}, E_{bb}, E_{cc}) and the orientations $(\theta_a, \theta_b, \theta_c)$.

- (b) Evaluate E_{11}, E_{22} and E_{12} for $\theta_a = 0^\circ$, $\theta_b = 60^\circ$, and $\theta_c = 120^\circ$.

Solution: (a) Given that the components of the strain measured in the directions $\{\mathbf{e}_a, \mathbf{e}_b, \mathbf{e}_c\}$ is

$$E_{aa} = \mathbf{e}_a \cdot \mathbf{E} \mathbf{e}_a, \quad E_{bb} = \mathbf{e}_b \cdot \mathbf{E} \mathbf{e}_b, \quad E_{cc} = \mathbf{e}_c \cdot \mathbf{E} \mathbf{e}_c \quad (1)$$

where the strain \mathbf{E} with respect to the basis $\{\mathbf{e}_1, \mathbf{e}_2\}$ can be defined as $\mathbf{E} = E_{ij} \mathbf{e}_i \otimes \mathbf{e}_j$. Thus Eq. (1) can be expressed as

$$\begin{aligned} E_{aa} &= \mathbf{e}_a \cdot (E_{ij} (\mathbf{e}_i \otimes \mathbf{e}_j) \mathbf{e}_a) \\ &= \mathbf{e}_a \cdot (E_{ij} (\mathbf{e}_j \cdot \mathbf{e}_a) \mathbf{e}_i) \quad \text{since } (\mathbf{e}_i \otimes \mathbf{e}_j) \mathbf{e}_a = (\mathbf{e}_j \cdot \mathbf{e}_a) \mathbf{e}_i \\ &= E_{ij} (\mathbf{e}_i \cdot \mathbf{e}_a) (\mathbf{e}_j \cdot \mathbf{e}_a) \\ \Rightarrow E_{aa} &= E_{11} (\mathbf{e}_1 \cdot \mathbf{e}_a) (\mathbf{e}_1 \cdot \mathbf{e}_a) + E_{12} (\mathbf{e}_1 \cdot \mathbf{e}_a) (\mathbf{e}_2 \cdot \mathbf{e}_a) + E_{21} (\mathbf{e}_2 \cdot \mathbf{e}_a) (\mathbf{e}_1 \cdot \mathbf{e}_a) + E_{22} (\mathbf{e}_2 \cdot \mathbf{e}_a) (\mathbf{e}_2 \cdot \mathbf{e}_a) \end{aligned}$$

Similarly E_{bb} and E_{cc} can be determined as

$$\begin{aligned} E_{bb} &= \mathbf{e}_b \cdot (E_{ij} (\mathbf{e}_i \otimes \mathbf{e}_j) \mathbf{e}_b) \\ &= \mathbf{e}_b \cdot (E_{ij} (\mathbf{e}_j \cdot \mathbf{e}_b) \mathbf{e}_i) \quad \text{since } (\mathbf{e}_i \otimes \mathbf{e}_j) \mathbf{e}_b = (\mathbf{e}_j \cdot \mathbf{e}_b) \mathbf{e}_i \\ &= E_{ij} (\mathbf{e}_i \cdot \mathbf{e}_b) (\mathbf{e}_j \cdot \mathbf{e}_b) \end{aligned}$$

$$\implies E_{bb} = E_{11}(\mathbf{e}_1 \cdot \mathbf{e}_b)(\mathbf{e}_1 \cdot \mathbf{e}_b) + E_{12}(\mathbf{e}_1 \cdot \mathbf{e}_b)(\mathbf{e}_2 \cdot \mathbf{e}_b) + E_{21}(\mathbf{e}_2 \cdot \mathbf{e}_b)(\mathbf{e}_1 \cdot \mathbf{e}_b) + E_{22}(\mathbf{e}_2 \cdot \mathbf{e}_b)(\mathbf{e}_2 \cdot \mathbf{e}_b),$$

and

$$\begin{aligned} E_{cc} &= \mathbf{e}_c \cdot (E_{ij}(\mathbf{e}_i \otimes \mathbf{e}_j)\mathbf{e}_c) \\ &= \mathbf{e}_c \cdot (E_{ij}(\mathbf{e}_j \cdot \mathbf{e}_c)\mathbf{e}_i) \quad \text{since } (\mathbf{e}_i \otimes \mathbf{e}_j)\mathbf{e}_c = (\mathbf{e}_j \cdot \mathbf{e}_c)\mathbf{e}_i \\ &= E_{ij}(\mathbf{e}_i \cdot \mathbf{e}_c)(\mathbf{e}_j \cdot \mathbf{e}_c) \\ \implies E_{cc} &= E_{11}(\mathbf{e}_1 \cdot \mathbf{e}_c)(\mathbf{e}_1 \cdot \mathbf{e}_c) + E_{12}(\mathbf{e}_1 \cdot \mathbf{e}_c)(\mathbf{e}_2 \cdot \mathbf{e}_c) + E_{21}(\mathbf{e}_2 \cdot \mathbf{e}_c)(\mathbf{e}_1 \cdot \mathbf{e}_c) + E_{22}(\mathbf{e}_2 \cdot \mathbf{e}_c)(\mathbf{e}_2 \cdot \mathbf{e}_c) \end{aligned}$$

From Fig. 1, the dot product between the basis vectors can be determined as follows:

$$\begin{aligned} \mathbf{e}_1 \cdot \mathbf{e}_a &= \cos \theta_a, & \mathbf{e}_1 \cdot \mathbf{e}_b &= \cos \theta_b, & \mathbf{e}_1 \cdot \mathbf{e}_c &= \cos \theta_c \\ \mathbf{e}_2 \cdot \mathbf{e}_a &= \sin \theta_a, & \mathbf{e}_2 \cdot \mathbf{e}_b &= \sin \theta_b, & \mathbf{e}_2 \cdot \mathbf{e}_c &= \sin \theta_c \end{aligned}$$

Thus the components of the strain measured in the directions $\{\mathbf{e}_a, \mathbf{e}_b, \mathbf{e}_c\}$ can be expressed as (by considering a symmetric tensor i.e, $E_{12} = E_{21}$) as

$$\begin{aligned} E_{aa} &= E_{11} \cos^2 \theta_a + 2E_{12} \cos \theta_a \sin \theta_a + E_{22} \sin^2 \theta_a \\ E_{bb} &= E_{11} \cos^2 \theta_b + 2E_{12} \cos \theta_b \sin \theta_b + E_{22} \sin^2 \theta_b \\ E_{cc} &= E_{11} \cos^2 \theta_c + 2E_{12} \cos \theta_c \sin \theta_c + E_{22} \sin^2 \theta_c, \end{aligned} \tag{2}$$

which can be expressed in the matrix form as

$$\begin{bmatrix} E_{aa} \\ E_{bb} \\ E_{cc} \end{bmatrix} = \begin{bmatrix} \cos^2 \theta_a & 2 \cos \theta_a \sin \theta_a & \sin^2 \theta_a \\ \cos^2 \theta_b & 2 \cos \theta_b \sin \theta_b & \sin^2 \theta_b \\ \cos^2 \theta_c & 2 \cos \theta_c \sin \theta_c & \sin^2 \theta_c \end{bmatrix} \begin{bmatrix} E_{11} \\ E_{12} \\ E_{22} \end{bmatrix}$$

Thus, the general expression for the components of strain, \mathbf{E} , (i.e E_{11} , E_{22} , $E_{12} = E_{21}$) with respect to the basis $\{\mathbf{e}_1, \mathbf{e}_2\}$ can be found as

$$\begin{bmatrix} E_{11} \\ E_{12} \\ E_{22} \end{bmatrix} = \begin{bmatrix} \cos^2 \theta_a & 2 \cos \theta_a \sin \theta_a & \sin^2 \theta_a \\ \cos^2 \theta_b & 2 \cos \theta_b \sin \theta_b & \sin^2 \theta_b \\ \cos^2 \theta_c & 2 \cos \theta_c \sin \theta_c & \sin^2 \theta_c \end{bmatrix}^{-1} \begin{bmatrix} E_{aa} \\ E_{bb} \\ E_{cc} \end{bmatrix} \tag{3}$$

(b) Given that $\theta_a = 0^\circ$, $\theta_b = 60^\circ$, and $\theta_c = 120^\circ$, the components of strain, E_{11} , E_{22} , E_{12} can be determined by substituting the values of θ_a , θ_b , θ_c in Eq. (3) as

$$\begin{bmatrix} E_{11} \\ E_{12} \\ E_{22} \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ \frac{1}{4} & \frac{\sqrt{3}}{2} & \frac{3}{4} \\ \frac{1}{4} & -\frac{\sqrt{3}}{2} & \frac{3}{4} \end{bmatrix}^{-1} \begin{bmatrix} E_{aa} \\ E_{bb} \\ E_{cc} \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ 0 & \frac{1}{\sqrt{3}} & -\frac{1}{\sqrt{3}} \\ -\frac{1}{3} & \frac{2}{3} & \frac{2}{3} \end{bmatrix} \begin{bmatrix} E_{aa} \\ E_{bb} \\ E_{cc} \end{bmatrix}. \tag{4}$$

The values of E_{11} , E_{22} , E_{12} can be found from Eq. (4) as

$$E_{11} = E_{aa}, \quad E_{12} = \frac{E_{bb} - E_{cc}}{\sqrt{3}}, \quad E_{22} = \frac{-E_{aa} + 2E_{bb} + 2E_{cc}}{3}.$$

3. Stress is not a directly measurable quantity for most materials and is usually computed from the strain measurements in a complex engineering system. A common method for measuring the state of strain is to use *strain gauges* which are simple electrical devices that can measure only the normal strain along its length.

A strain rosette having three strain gauges a, b and c is installed on a block as shown in Fig.2. During a static test of the block in plane strain ($\epsilon_{zz} = 0, \gamma_{xz} = 0$ and $\gamma_{yz} = 0$), the strain rosettes read $\epsilon_a = 0.003$, $\epsilon_b = 0.001$ and $\epsilon_c = 0.001$.

- 1) Calculate the shear strain γ_{xy} for an element oriented along the xy plane (Round your answer to 4 decimal points). Note that for a strain gauge oriented at an angle of θ to the x -axis, the gauge reading ϵ_θ can be expressed as:

$$\epsilon_\theta = \epsilon_{xx} \cos^2(\theta) + \epsilon_{yy} \sin^2(\theta) + \gamma_{xy} \sin(\theta) \cos(\theta)$$

- 2) If the block is made of a material with elastic modulus $E = 100$ GPa and Poisson's ratio $\nu = 0.3$, use Hooke's law to find the stress components in the $x - y$ plane.
- 3) Determine the principal stresses in the block.




Figure 2: Strain Gauges

Solution: We use the given strain transformation equation for each gauge:

- Gauge a ($\theta_a = 0^\circ$):

$$\begin{aligned}\epsilon_a &= \epsilon_{xx} \cos^2(0^\circ) + \epsilon_{yy} \sin^2(0^\circ) + \gamma_{xy} \sin(0^\circ) \cos(0^\circ) \\ 0.003 &= \epsilon_{xx}(1) + \epsilon_{xy}(0) + \gamma_{xy}(0) \\ \implies \epsilon_{xx} &= 0.003\end{aligned}$$

- Gauge b ($\theta_b = 90^\circ$):

$$\begin{aligned}\epsilon_b &= \epsilon_{xx} \cos^2(90^\circ) + \epsilon_{yy} \sin^2(90^\circ) + \gamma_{xy} \sin(90^\circ) \cos(90^\circ) \\ 0.001 &= \epsilon_{xx}(0) + \epsilon_{yy}(1) + \gamma_{xy}(0) \\ \implies \epsilon_{yy} &= 0.001\end{aligned}$$

- Gauge c ($\theta_c = 30^\circ$):

$$\begin{aligned}\epsilon_c &= \epsilon_{xx} \cos^2(30^\circ) + \epsilon_{yy} \sin^2(30^\circ) + \gamma_{xy} \sin(30^\circ) \cos(30^\circ) \\ 0.001 &= (0.003)(\cos 30^\circ)^2 + (0.001)(\sin 30^\circ)^2 + \gamma_{xy}(\sin 30^\circ)(\cos 30^\circ) \\ 0.001 &= (0.003)(0.75) + (0.001)(0.25) + \gamma_{xy}(0.5)(0.866) \\ 0.001 &= 0.00225 + 0.00025 + 0.433\gamma_{xy} \\ 0.001 &= 0.0025 + 0.433\gamma_{xy} \\ -0.0015 &= 0.433\gamma_{xy} \\ \implies \gamma_{xy} &\approx -0.0035\end{aligned}$$

First, calculate the shear modulus G :

$$G = \frac{E}{2(1 + \nu)} = \frac{100 \text{ GPa}}{2(1 + 0.3)} = 38.46 \text{ GPa}$$

The shear stress τ_{xy} is:

$$\tau_{xy} = G\gamma_{xy} = (38.46 \text{ GPa})(-0.0035) = -0.1346 \text{ GPa}$$

For plane strain ($\epsilon_{zz} = 0$), we use the 3D Hooke's Law equations:

$$\begin{aligned}\epsilon_{xx} &= \frac{1}{E}[\sigma_{xx} - \nu(\sigma_{yy} + \sigma_{zz})] \\ \epsilon_{yy} &= \frac{1}{E}[\sigma_{yy} - \nu(\sigma_{xx} + \sigma_{zz})] \\ \epsilon_{zz} &= \frac{1}{E}[\sigma_{zz} - \nu(\sigma_{xx} + \sigma_{yy})] = 0\end{aligned}$$

Substituting known values (with $E=100$ GPa):

$$\begin{aligned} 0.003 &= \frac{1}{100}[\sigma_{xx} - 0.3(\sigma_{yy} + \sigma_{zz})] \implies 300 = \sigma_{xx} - 0.3\sigma_{yy} - 0.3\sigma_{zz} \\ 0.001 &= \frac{1}{100}[\sigma_{yy} - 0.3(\sigma_{xx} + \sigma_{zz})] \implies 100 = \sigma_{yy} - 0.3\sigma_{xx} - 0.3\sigma_{zz} \\ 0 &= \frac{1}{100}[\sigma_{zz} - 0.3(\sigma_{xx} + \sigma_{yy})] \implies \sigma_{zz} = 0.3(\sigma_{xx} + \sigma_{yy}) \end{aligned}$$

Solving this system of 3 equations (all stresses in GPa):

- $\sigma_{xx} = 0.4615$ GPa
- $\sigma_{yy} = 0.3077$ GPa
- $\sigma_{zz} = 0.2308$ GPa

Since the problem is in plane strain ($\gamma_{xz} = 0, \gamma_{yz} = 0$), there are no shear stresses on the z-face. This means the z-axis is a principal direction.

Therefore, one of the principal stresses is σ_{zz} :

$$\sigma_{p2} = \sigma_{zz} = 0.2308 \text{ GPa}$$

The other two principal stresses, σ_{p1} and σ_{p3} , lie in the xy-plane. We find them using the center and radius of the Mohr's circle for the xy-plane:

$$\sigma_{ave} = \frac{\sigma_{xx} + \sigma_{yy}}{2} = \frac{0.4615 + 0.3077}{2} = 0.3846 \text{ GPa}$$

$$\begin{aligned} R &= \sqrt{\left(\frac{\sigma_{xx} - \sigma_{yy}}{2}\right)^2 + \tau_{xy}^2} \\ R &= \sqrt{\left(\frac{0.4615 - 0.3077}{2}\right)^2 + (-0.1346)^2} \\ R &= \sqrt{(0.0769)^2 + (-0.1346)^2} = 0.1550 \text{ GPa} \end{aligned}$$

The principal stresses are:

$$\begin{aligned} \sigma_{p1} &= \sigma_{ave} + R = 0.3846 + 0.1550 = 0.5396 \text{ GPa} \quad (\text{Max}) \\ \sigma_{p3} &= \sigma_{ave} - R = 0.3846 - 0.1550 = 0.2296 \text{ GPa} \quad (\text{Min}) \end{aligned}$$

So $\sigma_{p1} = 0.5396$ GPa, $\sigma_{p2} = 0.2308$ GPa, $\sigma_{p3} = 0.2296$ GPa.