


## **Spindle extention:**

Without an extension, chips will fall in the gearbox damaging the gears. To solve this problem, I made an extension. The end of the spindle has just enough threads to Mount an extension. The thread type is M27 x 1.5


### ***Spindle showing just enough threads to mount the extension:***



### ***The extension:***



***The extension mounted:***



***The cover mounted:***

