

SBOM Validation Report

Generated on: 2025-04-27 12:33:20.518979

Summary

Total discrepancies found: 0

Detailed Findings

Recommended Actions

1. Review all wire length discrepancies and update measurements
2. Verify twisted wire specifications match design requirements
3. Correct quantity mismatches in the BOM
4. Validate all connector pairings against the DPF
5. Check splice components for correct part numbers
6. Document all changes made during validation
7. Re-run validation after making corrections
8. Review high-priority issues first (marked in report)