

# RESIDENTIAL PROPERTY INSPECTION REPORT

**Dallas Home**

**4523 Oak Lawn Ave, Dallas, TX**

## ROOF SYSTEM

Roof shows normal weathering for age. No missing or damaged shingles observed. Flashing appears intact.



*Photo: ROOF SYSTEM*

## SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.