

RESIDENTIAL PROPERTY INSPECTION REPORT

San Diego Condo
1523 Garnet Ave, San Diego, CA

PLUMBING SYSTEM

Plumbing in excellent condition. No signs of corrosion or leaking at visible connections.



Photo: PLUMBING SYSTEM

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.