

# RESIDENTIAL PROPERTY INSPECTION REPORT

**Phoenix Home**  
**6789 E Camelback Rd, Phoenix, AZ**

## **ROOF SYSTEM**

Roof shows normal weathering for age. No missing or damaged shingles observed. Flashing appears intact.

## **SUMMARY**

Overall property condition is acceptable. Recommend standard monitoring and maintenance.