

## Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	Panel Pre Assy gas leak test
MN265	28	✓	none			✓	grey ✓ clear ✓	✓		✓
Repairs	PFN cleared replaced 2 clips (10/1, 10/11, 56/57, 92/93) → replaced (10/1) again ~									LT post PFN repair
HV issues	• 2 piece ch 0 HV side touch ch 1 • wire 1 high current • wire 10, 57, 92 are internal sparks • FeSS test - (V) • HV test - (V) • Gain test - (V) No blocked straws pass a cfort but need to repair 2 piece ch 0.									
Notes	• Air tested for blocked straws - ✓ • DMB gap test 45 mil Kapton and Air - ✓ • backside PFN check - ✓ epoxy in #1 • Ear flooding - ✓									