

# Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires/ straw	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	Panel pre. Assy gas leak test
mn 236	20	✓		85	85	✓	grey ✓ clear ✓	✓ ✓	✓	✓
Repairs	<ul style="list-style-type: none"> <li>epoxied on DMB - top corners - R+L</li> <li>ear flooded</li> </ul>									
HV issues	<ul style="list-style-type: none"> <li>No <math>\Omega</math> piece at straw 34/35</li> <li>gas leak at HV side and cal side of DMB</li> <li>high current</li> <li>HV test - ①</li> <li>gain test - ①</li> <li>Damage to 1 pin on Long connector on DMB</li> <li>piece missing at straw 34/35</li> </ul>									
Notes	<ul style="list-style-type: none"> <li>Air tested for blocked straws - ✓ OK</li> <li>DMB gap test w/ 5mil Kapton + Air - ✓ OK</li> <li>backside PFN check - ✓ OK</li> <li>standoffs are good ✓</li> </ul>									

inflatons: 1



04/08/25

MN 236

Missing 8+ saw : 85

High current wire : 35

Fe<sup>55</sup> ✓ Gain ✓ HV ✓

Kapton washers at all pins!