

Panel  
pre assy  
gas leak  
test

[illegible]



07-26-23:

Straw 71 has internal  
spark on Cal side.

Anode pin 76 missing

HV issues

MN 205

• Fe 55 test (V)

• HV test (V)

• gain test (V)

No pass QC  
test

• + block straw 19

• + anode wire 76 HV side missing

• +  $\Omega$  piece missing at Cal side 14, 17, 18

• + wire 28, 34, 36 no HV at Cal side

No pass QC test