

Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	Pre Assy gas leak test
mm 167	12	✓	Ø			✓	grey ✓ clear ✓	✓ ✓	✓	✓
Repairs										
HV issues	<div style="text-align: center;">01/28/2025</div> <div> <div>None!</div> <div>GAIN test done</div> </div> <div> <div>Kapton dots : 32, 33, 34, 35, 80, 81</div> <div>HV test ✓</div> <div>Gain test ✓</div> <div>Fe⁵⁵ test ✓</div> <div>All pins have Kapton washers except the above exceptions.</div> </div>									
Notes	Air test for blocked straws - ✓ Air tested + 5 mil Kapton check @ DMB connectors - good - ear goes in check gaps DMB Height @ connectors: Rt - $\frac{in}{out}$ Lft $\frac{in}{out}$ - <u>ear went in / did not measure</u> PFN ✓ = OK ear flooded									