

## Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	Panel Pre-Assy gas leak test
MN282	26	✓				✓	grey ✓ clear ✓	✓		✓
Repairs	<p>removed the PFN cap for PFN #7</p> <p>PFN Removed and replaced for #7. Audible crack heard after Arbor press.</p> <p>8/2/23 epoxy added between PIR and baseplate panel left straws ~10-26</p>									passed after PFN replacement
HV issues	<p>No blocked straw, all good!</p> <p>perm QC test</p> <p>FeSS test - (U)</p> <p>HV test - (U)</p> <p>Gain test - (U)</p>									
Notes	<p>Air test for blocked straws - ✓</p> <p>DMB gap test w/ 5mil kapton &amp; air - ✓</p> <p>backside PFN check - #7 is crooked</p> <p>ear flooding - ✓</p>									