

| Panel No | Plane No | Cleaned/ Prepped | Air test | Blocked straws | Missing wires | Missing wires confirmed | PFN epoxy | DMB Id | |
|--------------|--|---------------------|----------|-------------------|---------------|----------------------------|--------------|--------|------------------------------|
| ✓ MN048 | 8 | ✓ | X | 1(22) missing | 1 (22) | | ✓ | ✓ | car install ✓ Leak test ✓ |
| Repairs | car flooded. | | | | | | | | Pre Assy complete ✓ |
| HV issues | Sept. 11, 2024 • kapton dots: 82, 83, 86, 87 • <u>Parcel QC test</u> • Missing straws: 22 • Trip issue: 88 (Trips above 1400V) • Damaged DMB connected • HV test ✓ • Gain test ✓ • Fe SS ✓ | | | | | | | | |
| Notes | • Straw 22 cut out. Found a few scratches in the O-ring groove • AFns ✓ = OK | | | | | | | | |

stand off