

→ Sat in a window for 2 yrs

Pre Plane Assembly Summary

[illegible]

When installing in LTLT
straws 0, 2, 4 were moved by
neighboring ribbon when lowering.
Check 0, 2, 4 wire that they did
not become damaged in this process
8/14/24 DA



MN081:-

Wire spark : 10

Blocked wire : 11

Ch 45 → high current

Passed
QC test



7-8-24 Cramp for Channel II has a lead with
R. WAGNER NO SOCKET \rightarrow NEEDS REPAIR OR REPLACE.

\rightarrow All channels ARE QUIET: NO TRIPS OR
GLITCHES OR CURRENTS $\geq 1 \text{ nA}$.

\Rightarrow This is true at LOW K_H AND LOW FLOW
AT ROOM HUMIDITY $\leq 100\%$ SOME CURRENTS
INCREASE AT LOW FLOW.