

Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	Pre Assy gas leak test																
MN258	10	✓				✓	gray ✓ clear ✓	✓ ✓		✓																
Repairs	replaced omega clip																									
HV issues	<div><div><div>Ω piece channel 19 at HV side missing wire 1 short</div><table><thead><tr><th></th><th>wire 1</th><th>wire 17</th><th>wire 56</th></tr></thead><tbody><tr><td>Barode - cathode HV side</td><td>5.5 Ω</td><td>∞</td><td>∞</td></tr><tr><td>R anode - cathode Cal side</td><td>4.8 Ω</td><td>∞</td><td>∞</td></tr><tr><td>R anode - anode</td><td>55 Ω</td><td>142 Ω</td><td>114 Ω</td></tr></tbody></table></div><div>17.56 high current wire 90,91 internal spark.</div></div>											wire 1	wire 17	wire 56	Barode - cathode HV side	5.5 Ω	∞	∞	R anode - cathode Cal side	4.8 Ω	∞	∞	R anode - anode	55 Ω	142 Ω	114 Ω
	wire 1	wire 17	wire 56																							
Barode - cathode HV side	5.5 Ω	∞	∞																							
R anode - cathode Cal side	4.8 Ω	∞	∞																							
R anode - anode	55 Ω	142 Ω	114 Ω																							
Notes	<div>• Air tested for blocked straws - ✓ OK</div> <div>• DMB gap test w/ 5 mil kapton 3. air - ✓ OK</div> <div>• backside PFN check ✓ OK</div> <div>• Ear flooding - ✓</div>																									

Inflations