

Contoso Safety 360 Form

☒ Hazardous Condition

☐ At Risk Behavior

☒ Safety Suggestion

☒ Safety Recognition

☐ Equipment

☐ Material Handling

☐ Slips, Trips, Falls

☐ Spill, Release, Environmental

☒ Electrical

☐ PPE

☐ Ergonomics

☐ Other Safety

☒ Significant

☐ Not Significant

Findings: Electrical lines need to be reinspected as some workers reported cross wirings
Hairballs. This was discovered in electrical room 6-35.

Suggested Solutions: Examine and rewire electrical room 6-35 wiring and perform safety tests.
Sign offs are required by immediate supervisor.

Submitter: Hayat Hassen

Department: Manufacture floors **Date:** August 31, 2022

Owner: Sonila Rama

Solution Description: Suggested solutions are implemented. In addition, enhanced safety check list is defined. Periodic inspections will be performed.

Target Date: September 2, 2022 **Close Date:** September 3, 2022

Submitter Approval: Yes