

Contoso Safety 360

<input checked="" type="checkbox"/> Hazardous Condition	<input type="checkbox"/> At Risk Behavior	<input type="checkbox"/> Safety Suggestion	<input type="checkbox"/> Safety Recognition
---	---	--	---

<input checked="" type="checkbox"/> Equipment	<input type="checkbox"/> Material Handling
<input type="checkbox"/> Slips, Trips, Falls	<input type="checkbox"/> Spill, Release, Environmental
<input type="checkbox"/> Electrical	<input type="checkbox"/> PPE
<input type="checkbox"/> Ergonomics	<input checked="" type="checkbox"/> Other Safety

<input checked="" type="checkbox"/> Significant	<input type="checkbox"/> Not Significant
---	--

Findings: Mold plate was thrown out of CNC. Magnetic Plate was being used
Mold went through Plexi Glass Roof.

Suggested Solutions: Fix the equipment ab1, exam equipment room to make sure that
all safety conditions be met.

Submitter: Daleen du Plessis

Department: Tower Room

Date: July 26, 2021

Owner: Etleva Hysa

Solutions: Maintenance accident prevention team to work on solutions

Target Date: July 30, 2021

Close Date: July 29, 2021

Submitter Approval: Yes